University of Groningen

A patient with donning-related stump wounds

Baars, E. C. T.; Geertzen, J. H. B.

Published in:
Prosthetics and Orthotics International

DOI:
[10.1080/03093640802016738](https://doi.org/10.1080/03093640802016738)

IMPORTANT NOTE: You are advised to consult the publisher's version (publisher's PDF) if you wish to cite from it. Please check the document version below.

Document Version
Publisher's PDF, also known as Version of record

Publication date:
2008

[Link to publication in University of Groningen/UMCG research database](#)

Citation for published version (APA):

Baars, E. C. T., & Geertzen, J. H. B. (2008). A patient with donning-related stump wounds: A case report. *Prosthetics and Orthotics International*, 32(2), 219-222. <https://doi.org/10.1080/03093640802016738>

Copyright

Other than for strictly personal use, it is not permitted to download or to forward/distribute the text or part of it without the consent of the author(s) and/or copyright holder(s), unless the work is under an open content license (like Creative Commons).

The publication may also be distributed here under the terms of Article 25fa of the Dutch Copyright Act, indicated by the "Taverne" license. More information can be found on the University of Groningen website: <https://www.rug.nl/library/open-access/self-archiving-pure/taverne-amendment>.

Take-down policy

If you believe that this document breaches copyright please contact us providing details, and we will remove access to the work immediately and investigate your claim.

Downloaded from the University of Groningen/UMCG research database (Pure): <http://www.rug.nl/research/portal>. For technical reasons the number of authors shown on this cover page is limited to 10 maximum.

This article was downloaded by: [University of Groningen]

On: 4 August 2008

Access details: Access Details: [subscription number 787817372]

Publisher Informa Healthcare

Informa Ltd Registered in England and Wales Registered Number: 1072954 Registered office: Mortimer House, 37-41 Mortimer Street, London W1T 3JH, UK

Prosthetics and Orthotics International

Publication details, including instructions for authors and subscription information:

<http://www.informaworld.com/smpp/title~content=t714595820>

A patient with donning-related stump wounds: A case report

E. C. T. Baars MC ^a; J. H. B. Geertzen ^b

^a "De Vogellanden" Center for Rehabilitation, The Netherlands ^b University Medical Center Groningen, The Netherlands

First Published: June 2008

To cite this Article Baars MC, E. C. T. and Geertzen, J. H. B. (2008) 'A patient with donning-related stump wounds: A case report', *Prosthetics and Orthotics International*, 32:2, 219 — 222

To link to this Article: DOI: 10.1080/03093640802016738

URL: <http://dx.doi.org/10.1080/03093640802016738>

PLEASE SCROLL DOWN FOR ARTICLE

Full terms and conditions of use: <http://www.informaworld.com/terms-and-conditions-of-access.pdf>

This article may be used for research, teaching and private study purposes. Any substantial or systematic reproduction, re-distribution, re-selling, loan or sub-licensing, systematic supply or distribution in any form to anyone is expressly forbidden.

The publisher does not give any warranty express or implied or make any representation that the contents will be complete or accurate or up to date. The accuracy of any instructions, formulae and drug doses should be independently verified with primary sources. The publisher shall not be liable for any loss, actions, claims, proceedings, demand or costs or damages whatsoever or howsoever caused arising directly or indirectly in connection with or arising out of the use of this material.

A patient with donning-related stump wounds: A case report

E. C. T. BAARS¹ & J. H. B. GEERTZEN²

¹*“De Vogellanden” Center for Rehabilitation, The Netherlands, and* ²*University Medical Center Groningen, The Netherlands*

Abstract

A patient suffering from diabetes and a trans-tibial amputation presented with stump wounds caused by improper donning of the liner. His diminished hand function resulted in improper donning, with air being trapped between the liner and stump. This caused blisters on the skin after loading the prosthesis.

Keywords: *Stump wounds, liner, donning, hand function*

Introduction

A 62-year-old male patient with insulin dependent diabetes and a trans-tibial amputation on the left side, the result of necrotizing fasciitis after a burn injury 7 years ago, was seen in the outpatient clinic because of large blisters on the stump.

The patient had been seen a few weeks earlier because of shrinking of the stump volume and the sinking of the stump in the socket. The stump skin was in good condition with no wounds. The patient had experienced gradual deterioration of hand function, with diminished grip strength and sensation, during the years due to the diabetes, but claimed to have no difficulties in donning or doffing the prosthesis. He mentioned that he could not walk at all and only made transfers with his current prosthesis because of the poor fit, but wanted to start walking again. He also mentioned that his walking was unsure and only possible in the home with the assistance of his wife, because of a left hip fracture a few years ago and a diabetic right foot.

Initially, the patient had used a conventional prosthesis with thigh corset, but for the past 6.5 years he had used a Kondylen Bettung Münster (KBM)-type prosthesis with silicon liner. He had not previously complained of stump wounds. A new socket and tighter-fitting liner of the same type was prescribed. A week after the new socket and liner were delivered, the patient was seen with four large, open blisters on the distal part of the stump (Figure 1). The patient had had no trauma of the stump and only mentioned that, directly after delivery and donning the prosthesis and walking a short distance in the home, he noticed the blisters on his stump at the end of the day after taking off the prosthesis. We checked the donning technique

Correspondence: E. C. T. Baars, MC, Physiatrist, ‘De Vogellanden’ Center for Rehabilitation, Zwolle, The Netherlands.
E-mail: e.c.t.baars@vogellanden.nl

Figure 1. Blisters on the patient's stump.

of the patient and saw that he did not flatten the distal portion of the liner during application, instead applying it with a cup form with air trapped between the liner and stump. The skin sensitivity of the stump (checked by brushing the skin lightly) was clearly diminished. The wounds were treated and healed a week later, after which the stump was formed with a compression liner. A thicker, looser-fitting and softer liner was applied for use in the prosthesis. The patient could turn the liner inside out and flatten the distal portion of the liner against the stump adequately and was instructed to do so every time he donned the prosthesis. No air was trapped and he could function adequately afterwards. No wounds were seen during the subsequent consultations.

Discussion

This case report shows that proper donning technique of a silicon liner is essential, and that improper donning with air becoming trapped distally can easily cause large blisters to form on the distal stump skin. With this patient, the donning technique was not evaluated before a new socket and liner were prescribed. Also, the patient did not mention having trouble with donning. In our experience, this is often the case with patients who have experienced (gradual) deterioration of hand function, and such patients should be asked explicitly if donning the prosthesis is a problem. A demonstration of the donning technique by the patient can be very informative.

We assume that the old liner, which did not have a good fit, let any trapped air escape proximally during loading of the prosthesis. The tighter new liner caused air to be trapped that could not escape and, during the loading response of the prosthesis, this air heated and caused skin temperature to rise (bike-pump phenomenon). The pattern of blister formation, forming a circle on the distal end of the stump, shows that friction on the skin also plays an important role. Because of the air becoming trapped distally, the liner loses contact with the skin in a circular pattern. This results in shearing forces taking effect because of the loosening of liner contact with the skin. This effect, in combination with the elevated skin temperature, causes blisters. Blisters can form quickly, especially when the shearing forces are combined with elevated skin temperature (Levine 1982; Zhang et al. 1994). The fact that the patient could not walk with his old prosthesis protected him from developing these blisters because the prosthesis was not loaded; thus, the trapped air was not heated and friction forces remained minimal.

The new liner we prescribed was softer, more pliable, could be handled more easily, and had also a looser fit so that any trapped air could escape. The patient could resume walking short distances in his home with two crutches, but did not reach his original level of walking because of his long period of inactivity, in combination with the progression of the diabetes.

The literature pays little attention to the donning and doffing of lower-limb prostheses. There are only a few studies that mention donning, and that in relation to a larger study objective. For example, in one paper comparing the function of a KBM prosthesis with the function of the liner prosthesis, mention is made of the ease of donning the different fitting systems (Cluitmans et al. 1994; Datta et al. 1996; Yiğiter et al. 2002). Gauthier-Gagnon et al. (1999) state that the donning of a prosthesis is an enabling factor for use of the prosthesis, and that more than 8% of the trans-tibial patients have problems, while more than 3% need help. Difficulties in donning can be caused by deficiencies in the upper limb, either of strength or of dexterity, and impaired vision (Cochrane et al. 2001). In addition, diminished sensation in the fingers and hemiplegia can cause problems (Hachisuka et al. 1998). In previous research, we have found that impaired hand function poses an increased risk for skin problems in the stump (Baars et al. in press). To facilitate donning, different solutions have been developed in the form of a special prosthesis suspension table or donning apparatus (Figuroa et al. 1980; Tamir et al. 2003). In light of these studies and our case report, it is odd to note that experts in the field of amputation and prosthesis in The Netherlands do not seem to regard donning and doffing as a primary influence on prosthetic prescription (Van Der Linde et al. 2004).

In our opinion, donning of the prosthesis is an essential prerequisite for safe use and this should be considered when prescribing a prosthesis. Not only is optimal function of the prosthesis dependent on a proper donning technique, but also stump-skin integrity. Blisters can form quickly, especially when the skin temperature is elevated (Levine 1982). The large blisters shown in this case report appeared quickly as the result of one-time improper donning.

Conclusions

The lesson to be learned from this case report is that an improper donning technique can result in a serious stump-skin complication. It is important to take time and observe the prosthesis donning and doffing techniques of the patient, especially if the hand function is compromised. If proper instruction does not lead to an adequate result, the prosthetic prescription must be adapted to facilitate safe donning. In the case of a liner, one should think of using a softer, more pliable liner to facilitate the flattening of the distal cup of the liner so that a proper application to the stump can be achieved and the risk of air being trapped can be eliminated.

Declaration of interest: The authors report no conflicts of interest. The authors alone are responsible for the content and writing of the paper.

References

- Baars ECT, Dijkstra PU, Geertzen JHB. Skin problems of the stump and hand function in lower limb amputees: a historic cohort study. *Prosthet Orthot Int* (in press).
- Cluitmans J, Geboers M, Deckers J, Rings F. 1994. Experiences with respect to the ICEROSS system for trans-tibial prosthesis. *Prosthet Orthot Int* 18:78–83.
- Cochrane H, Orsi K, Reilly P. 2001. Lower limb amputation Part 3: Prosthetics—a 10 year literature review. *Prosthet Orthot Int* 25:21–28.
- Datta D, Vaidya SK, Howitt J, Gopalan L. 1996. Outcome of fitting an ICEROSS prosthesis: views of trans-tibial amputees. *Prosthet Orthot Int* 20:111–115.

- Figuroa C, Rivera D, Wainapel SF. 1980. Table to facilitate donning stubby prostheses by bilateral above-knee amputees. *Phys Ther* 60:909–911.
- Gauthier-Gagnon C, Grisé MC, Potvin D. 1999. Enabling factors related to prosthetic use by people with transtibial and transfemoral amputation. *Arch Phys Med Rehabil* 80:706–713.
- Hachisuka K, Dozono K, Ogata H, Ohmine S, Shitama H, Shinkoda K. 1998. Total surface bearing below-knee prosthesis: advantages, disadvantages, and clinical implications. *Arch Phys Med Rehabil* 79:783–789.
- Levine N. 1982. Friction blisters. *The physician and sportsmedicine* 10:84–92.
- Tamir E, Heim M, Oppenheim U, Siev-Ner I. 2003. An assistive device designed to convey independent donning of a shuttle lock trans-tibial prosthesis for a multiple limb amputee. *Prosthet Orthot Int* 27:74–75.
- Van Der Linde H, Geertzen JHB, Hofstad CJ, Limbeek v J, Postema K. 2004. Prosthetic prescription in the Netherlands: an interview with clinical experts. *Prosth Orthot Int* 28:98–104.
- Yığiter K, Şenar G, Bayar K. 2002. Comparison of the effects of patellar tendon bearing and total surface bearing sockets on prosthetic fitting and rehabilitation. *Prosthet Orthot Int* 26:206–212.
- Zhang M, Turner-Smith AR, Roberts VC. 1994. The reaction of skin and soft tissue to shear forces applied externally to the skin surface. *Proc Instn Mech Engrs* 208(Part H):217–222.